



Appendix A

Photographs



**US Army Corps
of Engineers**
Norfolk District

Chesapeake
VIRGINIA

Department of Public Works

URS



Photo 1. Downstream of Butts Station Road - Looking at West Bank's Road Drainage



Photo 2. Downstream of Butts Station Road - Looking upstream



Photo 3. Downstream of Butts Station Road - Looking upstream



Photo 4. Downstream of Butts Station Road - Looking upstream



Photo 5. Downstream of Butts Station Road - Looking downstream



Photo 6. Upstream End of Greystone - Looking upstream



Photo 7. Upstream End of Greystone - Looking downstream

Comment: Drainage channel starts to meander.



Photo 8. Greystone Road Drainage Outfall

Comment: Scour hole present.