




Certification of Correct Functioning

Approach: CHE-BAKE-01 NB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at North bound, Battlefield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 10-2-17
Notary Date






Certification of Correct Functioning

Approach: CHE-GRKE-01 SB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at South bound, Kempsville/Butts Station Rd. and Greenbrier Pkwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 10-2-17
Date





Certification of Correct Functioning

Approach: CHE-IRSP-01 EB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at East bound, Indian River Rd. and Sparrow Rd. in Chesapeake, Virginia was operating normally.



Shannan Moore

10.2.17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary

10-2-17
Date






Certification of Correct Functioning

Approach: CHE-KEBA-01 WB


City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at West bound, Battlerfield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 10-2-17
Date






Certification of Correct Functioning

Approach: CHE-MIGR-01 SB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 10-2-17
Notary Date






Certification of Correct Functioning

Approach: CHE-MIGR-01A SB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 10-2-17
Date






Certification of Correct Functioning

Approach: CHE-POGU-01 WB


City: CHESAPEAKE

Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at West bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.



Shannan Moore

10-2-17
Date


Notary

10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems





Certification of Correct Functioning

Approach: CHE-POPE-01L EB

City: CHESAPEAKE


Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 10-2-17
Date






Certification of Correct Functioning

Approach: CHE-POPE-01R EB

City: CHESAPEAKE

Date: September 2017

I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Shannan Moore 10-2-17
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 10-2-17
Date

