



Certification of Correct Functioning

Approach: CHE-BAKE-01 NB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at North bound, Battlefield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date






Certification of Correct Functioning

Approach: CHE-GRKE-01 SB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at South bound, Kempsville/Butts Station Rd. and Greenbrier Pkwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date






Certification of Correct Functioning

Approach: CHE-IRSP-01 EB City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at East bound, Indian River Rd. and Sparrow Rd. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date






Certification of Correct Functioning

Approach: CHE-KEBA-01 WB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at West bound, Battlerfield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 7-10-18
Date






Certification of Correct Functioning

Approach: CHE-MIGR-01 SB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 7-10-18
Date






Certification of Correct Functioning

Approach: CHE-MIGR-01A SB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date





Certification of Correct Functioning

Approach: CHE-POGU-01 WB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at West bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date






Certification of Correct Functioning

Approach: CHE-POPE-01L EB

City: CHESAPEAKE


Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date






Certification of Correct Functioning

Approach: CHE-POPE-01R EB

City: CHESAPEAKE

Date: June 2018

I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Shannan Moore 7-10-18
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Irene Frye 7-10-18
Notary Date

