




Certification of Correct Functioning

Approach: CHE-BAKE-01 NB


City: CHESAPEAKE

Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at North bound, Battlefield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date


Notary 7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-BAVO-01SB

City: CHESAPEAKE


Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at South bound, Battlefield Blvd and Volvo Pkwy in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 7/20/22
Date






Certification of Correct Functioning

Approach: CHE-CAMI-01 SB

City: CHESAPEAKE


Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at South bound, Canal Rd and Military Hwy in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 7/20/22
Date





Certification of Correct Functioning

Approach: CHE-GRKE-01 SB

City: CHESAPEAKE


Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at South bound, Kempsville/Butts Station Rd. and Greenbrier Pkwy. in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary

7/20/22
Date






Certification of Correct Functioning

Approach: CHE-GRVO-01 SB

City: CHESAPEAKE


Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbriar Pkwy and Volvo Pkwy in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary 7/20/22
Date






Certification of Correct Functioning

Approach: CHE-GRVO-02 NB


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at North bound, Greenbrier Pkwy and Volvo Pkwy in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date


Notary

7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-IRSP-01 EB


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at East bound, Indian River Rd. and Sparrow Rd. in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date


Notary

7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-KEBA-01 WB


City: CHESAPEAKE

Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at West bound, Battlefield Blvd. (Rt. 168) and Kempsville Rd. in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date


Notary 7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-MIGR-01 SB


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date


Notary

7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-MIGR-01A SB

City: CHESAPEAKE


Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at South bound, Greenbrier Pkwy/Dunbarton and Military Hwy. in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems


Notary

7/20/22
Date






Certification of Correct Functioning

Approach: CHE-MIGW-02 WB


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at west bound, George Washington Hwy and Military Hwy in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date


Notary

7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-POGU-01 WB


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at West bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.



Monica Pop

7-20-22
Date


Notary

7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-POPE-01L EB


City: CHESAPEAKE

Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date

 7/20/22
Notary Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-POPE-01R EB


City: CHESAPEAKE

Date: June 2022


I certify that a review of the maintenance records conclude the camera system located at East bound, Gum Road/Peek Trail and Portsmouth Bl. in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date


Notary 7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems






Certification of Correct Functioning

Approach: CHE-TAPO-01


City: CHESAPEAKE

Date: June 2022

I certify that a review of the maintenance records conclude the camera system located at Taylor Rd and Portsmouth Blvd. in Chesapeake, Virginia was operating normally.


Monica Pop

7-20-22
Date


Notary 7/20/22
Date

Corporate Co-Custodian of Record
Redflex Traffic Systems

